



# Digital. Accurate. Accountable.

# Total Control, Every Port


## About Us

We specialize in precision-driven vehicle cargo inspections, ensuring every vehicle is documented, protected, and accounted for from port arrival to final destination. Our skilled teams use advanced tools, GPS-stamped photo reporting, digital checklists, and real-time dashboards, to capture every detail, from minor blemishes to full-surface damage mapping. We combine meticulous inspections.

## Why Choose Us?

To deliver precision cargo services across multiple sectors, combining experienced teams, innovative technology, and a proactive approach to keep operations running at peak efficiency. Our reputation is built on accuracy, transparency, and results.

**one team, total control, every port.**



Record sound conditions, or damages, of vehicles being handled, during logistics or onboard the vessel

**"From bumper to bumper, we inspect, record, and protect your vehicle shipments with unmatched precision."**



### Full-Surface Damage Vehicle Mapping

Every vehicle is inspected from front to back, top to bottom, with damage clearly documented and labeled by position (e.g., bumper, door, roof). Each survey includes visual vehicle diagrams that indicate where damage is located



### Photo-Verified Condition Reports

Using a specialized inspection app, we take time-stamped, GPS-tagged photos of all damage to ensure proof of condition at time of survey.



### Mobile Inspection App

Our surveyors use a custom-built app to log all defects, damage types, and panel locations directly from the field—minimizing errors and maximizing speed.



### Digital Stow Plan

Each Vehicle that is loaded is allocated a position when captured, generating a digital stow plan on completion of operations.



### Real-Time Reports

All reports are tied to specific shifts, tally clerks, and vessel details, and can be viewed live via client dashboard or downloaded in PDF format.



### Digital Checklist & Condition Summary

Each inspection ends with a digital checklist, highlighting all pass/fail items — including tyres, lights, mirrors, and more — for a complete overview.



**INSIGHT**  
CARGO SOLUTIONS

 <https://www.insightcargosolutions.co.za/>

 [Inquiries@insightcargosolutions.com](mailto:Inquiries@insightcargosolutions.com)



## New car

22 January 2026 09:45 (+02:00)

## Ro-Ro Inspection

Site	GQEBERHA EM
Activity time	22 January 2026 09:45 (+02:00)

Comments	
----------	--

## FRONT



Front Bumper condition: **dented**

Windscreen condition: **cracked**



## RIGHT SIDE

Right Back Tire (Wheel) condition: **thread**



Vehicle ID	WWZZZAWSTUO48832
------------	------------------

Tally clerk	SAMUEL
-------------	--------

## Checklist

✘ Front Bumper condition FRONT: dented	✔ Bonnet condition
✔ Right Front Fender condition	✔ Right Front Tire (Wheel) condition
✘ Windscreen condition FRONT: cracked	✔ Windshield Wipers and Washers condition
✔ Left Front Fender condition	✔ Left Front Tire (Wheel) condition
✔ Roof condition	✔ Right Front Door condition
✔ Right Front Window condition	✔ Right Back Door condition
✔ Right Back Window condition	✔ Right Side Skirts condition
✔ Left Front Door condition	✔ Left Front Window condition

# SITREP Consolidated Ro-Ro Inspection

Site	GQEBERHA EM
Vessel	Mv Envision Maritime
Voyage in/out	60/60
Arrival	4 Dec 2025
Departure	6 Dec 2025

Inspected	Sound	Damaged
612	540	72

## DAMAGES

Type	Count
New car: Roof condition	12
New car: Left Front Tire (Wheel) condition	11
New car: Right Front Tire (Wheel) condition	9
New car: Left Front Door condition	7
New car: Windscreen condition	7
New car: Right Front Door condition	7
New car: Right Back Tire (Wheel) condition	6
New car: Front Bumper condition	6
New car: Boot (Trunk) condition	4
New car: Left Back Tire (Wheel) condition	4
New car: Rear Bumper condition	4
New car: Left Front Window condition	3
H/H high and heavy: Roof condition	3
New car: Bonnet condition	3
New car: Left Back Door condition	3
New car: Windshield Wipers and Washers condition	3
New car: Right Front Window condition	3

### H/H high and heavy / Sound: 9 / Damages: 6

#### H/H high and heavy: Roof condition (3)

Vehicle ID	Brand	Type	Condition	Comment	Photos
<a href="#">1L06110MKS541168</a>		H/H high and heavy		TOP: Antenna Damaged	
<a href="#">1L06110MCS542168</a>		H/H high and heavy		TOP: Roof Damaged	
<a href="#">1L06140OMT544098</a>		H/H high and heavy		TOP: Antenna damaged	

#### H/H high and heavy: Front Bumper condition (1)

Vehicle ID	Brand	Type	Condition	Comment	Photos
<a href="#">A9605496</a>		H/H high and heavy		FRONT: Cracked and dented	


#### H/H high and heavy: Windscreen condition (1)

Vehicle ID	Brand	Type	Condition	Comment	Photos
<a href="#">1L06125MJSE540971</a>		H/H high and heavy		FRONT: Windscreen cracked	

# SITREP Ro-Ro Discharge and Load

Site	GQEBERHA EM
Vessel	Mv Envision Maritime
Voyage in/out	60/60
Arrival	4 Dec 2025 06:00
Departure	6 Dec 2025 06:00

	Plan	Actual	Balance	Over-handled
Discharge, Vehicle	522	521	1	0
Load, Vehicle	85	84	1	0



## LOAD DECKS SUMMARY

Deck	Loaded	Load weight
1	22	27,016
2	20	24,560
3	21	25,788
4	11	13,508
5	10	12,280

## RESTOW DECKS SUMMARY

Deck	Direct	Direct weight	Indirect	Indirect weight
1				
2				
3				
4				
5				

## HOURLY PRODUCTIVITY

Hour	Discharged	Loaded	Restowed	Total
04 Dec 10h	18	0	0	18
04 Dec 11h	39	0	0	39
04 Dec 12h	39	0	0	39
04 Dec 13h	110	0	0	110
04 Dec 14h	44	0	0	44
04 Dec 16h	0	84	0	84
08 Dec 13h	86	0	0	86
08 Dec 14h	119	0	0	119
08 Dec 15h	61	0	0	61
19 Jan 14h	5	0	0	5

## VEHICLE TYPE

### DISCHARGE

Vehicle	Discharged	Damaged
H/H high and heavy	17	8
New car	502	51
Statics on 62' Mafi	2	

### LOAD


Vehicle	Loaded	Damaged
New car	84	15

## SHIFTS DISCHARGE SUMMARY

Shift	Discharged
04 Dec 06-18	250
08 Dec 06-18	266
19 Jan 06-18	5

## SHIFTS LOAD SUMMARY

Shift	Deck	Loaded
04 Dec 06-18	1	22
04 Dec 06-18	2	20
04 Dec 06-18	3	21
04 Dec 06-18	4	11




## DECK 1 STOWAGE PLAN

Filter by Block#	Vehicle ID	Block#	Athwartship	Weight	Discharge	Description	Condition	Photos
All blocks	WWWZZZAW9TU024492	1	Yes	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU024723	1	Yes	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU024730	1	Yes	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU024234	1	No	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU025882	1	No	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU020941	1	No	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU027426	2	Yes	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU027130	2	Yes	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU031048	2	No	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU031059	2	No	1228	AUFRE	Final destination: AUFRE, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU029812	3	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU030044	3	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU030299	4	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030547	4	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030971	4	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030358	4	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU030593	4	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU030748	5	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030797	5	Yes	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030556	5	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	IN GOOD ORDER	
	WWWZZZAW9TU030647	5	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	
	WWWZZZAW9TU030601	5	No	1228	AUMEL	Final destination: AUMEL, BookNo: ZA019778, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:	DAMAGED	

## DISCHARGE PORTS

Destination port	Total	Loaded	Balance	Restowed
AUFRE	10	10		
AUMEL	64	64		
AUPKL	11	10	1	
N/A	0			
<b>Grand total</b>	<b>85</b>			



LATEST  
**SMART-EX 02 SERIES**  
 100% IN-HOUSE DEVELOPMENT  
 The State-of-the-Art Smartphone  
 for Global Hazardous Areas

ZONE 1/21 DZ1 ZONE 2/22 DZ2 RUGGED

## DISCREPANCIES

## SHORT-SHIPMENT

Vehicle ID	Weight	Discharge	Description
1 WWWZZZAWXTU033413	1228	AUPKL	Final destination: AUPKL, BookNo: ZA019777, Sub: 0001, BL number: , Customer: GEVW, Propulsion: F, New: Y, Type: CA, Description: VW POLO, Comments:

## SHORT-LANDED

Vehicle ID	Weight	Discharge	Description
1 1L06140MTSG544098	1228		Loadport: BEANR, Booking: GE083955, Sub: 0009, BL no: HOEGNH60ANPZ2002, Customer: GEDEEREMA, Type: HH, Description: * JOHN DEERE TRACTOR 6M 140 TIER 2 CAB, Propulsion: F, Next transport: N/A, Next discharge: Dep.date:


## OVER-LANDED

Vehicle ID	Weight	Discharge	Description	Condition	Photos
------------	--------	-----------	-------------	-----------	--------

Deck 1

HEIGHT OPTIONS

- 2100 mm
- 2300 mm
- 4000 mm



Cluster Load, Vehicle   
 Deck# Deck 1   
 POL Port Elizabeth

	Hold 1		Hold 2		Total Quantity	Total Weight (Mt)
	Quantity	Weight (Mt)	Quantity	Weight (Mt)		
<b>AUFRE</b>						
VW POLO			10	12,28	10	12,28
<b>AUMEL</b>						
VW POLO	9	11,052	3	3,684	12	14,736
<b>Grand Total</b>	<b>9</b>	<b>11,052</b>	<b>13</b>	<b>15,964</b>	<b>22</b>	<b>27,016</b>

Cluster Restow, Vehicle   
 Deck# Deck 1

	Hold 1	Hold 2	Grand Total
<b>Total</b>	<b>13</b>	<b>9</b>	<b>22</b>

